WJE

PERSONNEL QUALIFICATIONS

Leah M. Ruther | Senior Associate



EDUCATION

- Calvin College
 - Bachelor of Science, Civil Engineering, 2011
- Lawrence Technological University
- Master of Civil Engineering, 2013

PRACTICE AREAS

- Repair and Rehabilitation Design
- Structural Evaluation
- Damage Assessment and Documentation
- Fire Damage Investigation
- Construction Observation Services
- Facade Assessment
- Testing and Instrumentation
- Roofing and Waterproofing

REGISTRATIONS

Professional Engineer in MI

PROFESSIONAL AFFILIATIONS

 Structural Engineers Association of Michigan - Young Members Chapter

CONTACT

Iruther@wje.com 734.660.3612 www.wje.com

EXPERIENCE

Since joining WJE in 2012, Leah Ruther has been involved in numerous projects related to both structural engineering and architecture. Her typical responsibilities have included the investigation and analysis of existing and damaged structures, development of technical repair and rehabilitation documents, and construction observations. Ms. Ruther has performed a variety of structural analyses on steel, concrete, masonry, and wood structures. She has assisted with several nondestructive investigations and completed multiple condition assessments. Additionally, Ms. Ruther has performed multiple water infiltration investigations.

REPRESENTATIVE PROJECTS

Repair and Rehabilitation Design

- First Baptist Church Oak Park, MI: Repair of masonry walls, wood trusses, and roofing with preparation of construction drawings
- Two Pierce Place Parking Garage Itasca, IL: Concrete repairs with preparation of construction drawings
- CC Little Ann Arbor, MI: Waterproofing and masonry repairs with technical documentation preparation and construction observation services

Structural Evaluation

- Paul Building Grand Rapids, MI: Roof collapse investigation and analysis; repair design and preparation of repair documents
- Major Retail Store Chain Various Locations: Field inspection, structural analysis, repair recommendations, and design for large metal-frame buildings
- Granger Energy of Morgantown -Morgantown, PA: CMU wall and concrete foundation design

Damage Assessment and Documentation

- Hagelstein Bakery Royal Oak, MI: Structural evaluation of partial wall collapse, shoring design, and preparation of repair documents
- Kamps Hardwood Grand Rapids, MI: Structural evaluation of partial roof collapse

Fire Damage Investigation

Residential Home - Whitehall, MI: Structural assessment of fire damage to wood trusses followed by repair design and preparation of repair documents

Construction Observation Services

- Varsity Tennis Ann Arbor, MI: Preparation of repair documents for subgrade waterproofing of the concrete foundation and construction observation services
- Metropolitan United Methodist Church Parsonage - Huntington Woods, MI: Preparation of repair documents for masonry repairs and roof replacements; construction observation services

Facade Assessment

- Fox Theater Parking Garage Detroit, MI: Condition assessment and report of findings submitted to owner and City of Detroit to satisfy facade ordinance requirements
- Simpson Circle Parking Structure Cooling Tower Enclosure - Ann Arbor, MI: Condition assessment with technical document preparation and construction services

Testing and Instrumentation

 Prescott Valley Public Library - Prescott Valley, AZ: Field investigation and water infiltration testing of metal roofing system

Roofing and Waterproofing

 35th Macomb Centre - Clinton Township, MI: Condition assessment and design of EPDM membrane roofing system

